

From: [Crossland, Ronnie](#)
To: [Leonova, Larisa](#); [R6HarveyENVL](#)
Cc: [Bernier, Roberto](#)
Subject: RE: list of items needed from Arkema
Date: Saturday, September 2, 2017 9:11:16 PM

Larisa,

Please proceed with modeling effort when you have the information from Arkema to proceed.

Please let me know if you don't have what was promised from Arkema.

Thanks

Ronnie

From: Leonova, Larisa
Sent: Saturday, September 02, 2017 7:54 PM
To: R6HarveyENVL
Cc: Crossland, Ronnie ; Bernier, Roberto
Subject: RE: list of items needed from Arkema
Updated list

From: R6HarveyENVL
Sent: Saturday, September 02, 2017 6:37 PM
To: Leonova, Larisa <leonova.larisa@epa.gov>
Subject: Re: list of items needed from Arkema

From: Leonova, Larisa
Sent: Saturday, September 2, 2017 5:43 PM
To: Crossland, Ronnie
Cc: R6HarveyENVL
Subject: list of items needed from Arkema

1. SO2 container/storage location
2. Distance between the isobutylene container and the SO2 container/storage location
3. Distance between the 6 containers with organic peroxides and the SO2 container/storage location
4. Identify the other chemicals of concern (flammable, combustible, high concentration acids, etc), TSCA and FIFRA products presence on Arkema's territory and provide the concentrations and quantities of these products/chemicals.
5. SDSs for products that may be in #4 (chemicals of concern)
6. Any other information that may be important/valuable for modeling of possible chemical releases and fires

Larisa Leonova, Ph.D
Chemist, Tech. Adviser
US EPA-R5-LCD-CMB
77 W. Jackson Blvd. LC-17J
Chicago, IL 60604
312-353-5838 Phone
312-408-2219 Fax
202-578-3043 Work Cell